TECHNICAL PUBLICATION INFORMATION

TO SERVICE SECTION
TO COMMUNICATIONS SECTION

Date: August 2007

MODEL	F75C
SUBJECT	SERVICE MANUAL CORRECTION

Incorrect information was included in the current Service Manual.
Please make an appropriate correction using the information that is provided herein.

Applicable Service Manual
6BC-28197-5K-11

INCORRECT

CORRECT

<P4-20>

Checking the fuel pump

<Figure of step 4-5 (Right column)>

Fuel pump outlet ③



Specified positive pressure:
50 kPa (0.5 kgf/cm², 7.3 psi)



Specified positive pressure:
50 kPa (0.5 kgf/cm², 7.3 psi)